

TOG NEWS INDEX

Issues 1 - 60 (FALL 1993)

ABYC	60:70	28:2 30:2 39:22 41:62 55:14
ADHESIVES	53:61	DECKS AND HARDWARE	
ANCHORS	6:8 29:6 29:13 42:75	Binnacle	36:17
Anchor rollers	25:10 26:10 27:8 44:100 44:102 44:104	Cleaning	42:83
Anchoring hints	8:12 9:15 18:5 21:9 21:14 23:7 35:8	Delamination	13:11 42:90
.....	42:75	Drainage	56:22
Bruce	19:12 23:6 28:7 31:15 31:16 37:14 43:96	Lifelines	43:94
Chain, chain lockers	48:17 51:47 55:14 56:22 58:45	Mast guards	31:4
Plow	6:8 11:11 13:5 19:12 21:9 21:14	Molding	31:4
.....	23:6 25:9 26:10 28:7 37:15	Nonskid	40:50
Danforth	11:11 13:5 21:9 26:9 28:7	Paint removal	33:7
Luke	28:7	Pilot House Skylight	44:102
Northill	23:7	Traveler, main	3:2 4:3 5:2 9:7 3:11
Stern anchors	47:14	14:8 16:8 17:7 30:6
BELOW DECKS		Traveler, staysail	13:11 14:12 16:7
Air conditioning	38:6 41:61 52:53	Washdown	52:53
Cabinet hinges	48:17	DEPTH SOUNDERS	13:5 28:14 30:8 40:46 21:4
Cabin Light	54:6	DINGHY ...	15:3 16:2 18:15 18:16 19:21 25:6 32:16 33:8 37:11
Condensation / ventilation	32:15 49:29 49:30	Davits	29:15 35:16
Electric mattress	44:100	DISASTERS	
Entertainment center	30:5	Cabo San Lucas	18:1
Fireplace	38:6	Capsize	12:4
Insulation	56:22 56:23	Collision	21:6 24:6 24:8
Lee Cloths	51:43	Fire	22:7 51:41 56:26
Navigation. station	52:50	Grounding	21:6 21:7 29:6 43:91 59:56
Spice rack	60:70	Hurricane	22:7 26:6 49:27 58:44
Storage	29:18 31:6 44:100 44:102 52:55 54:7 56:24	Lightning	23:14
Washer/dryer	38:6	Loss	22:7
BLISTERS	22:12 23:3 29:16 31:3 32:1 35:11 35:12	DODGER, WEATHER CLOTHS	34:5 43:97 49:28 51:43
.....	36:1 36:16 37:7 39:32 39:33 40:46 40:47	52:50 56:22
.....	42:82 43:92 44:106 51:47 56:21 57:34 58:51 60:70	ELECTRICAL	
BOAT SWAPPING	1:1 23:1 31:15	Alternators	34:9 34:11 36:15 37:12 40:45 42:83 43:97
BOAT US	10:2 10:8 12:9 16:4 16:12 26:18	Ammeters, gauges	36:12 45:111
.....	27:1 28:17 54:8 55:10	Batteries, charging	30:7 34:9 37:6 37:12 42:83
BOOM GALLOWS	34:17 13:11 14:3	Generators	28:6 34:11 38:6 52:53 58:51
BOOM, MAIN	2:3 8:10 14:4	Inverters	38:18 42:82 43:96 47:13
BOOM, STAYSAIL ...	2:4 11:16 14:4 16:2 16:10 17:2 17:7 19:6	Regulator	40:45
.....	21:14 23:16 25:4 25:14 26:7 27:8 29:5	Solenoid	42:88
.....	29:15 37:17 39:31 53:58 58:51	Solar panels	47:12 49:28
BOTTOM CARE	32:13 36:10 36:16 38:15 42:88	Wind / water generators	28:6 55:12
BOWSPRIT	6:10 8:10 31:6 39:35 49:26 60:68	Wiring	9:12 10:18 18:13 18:14 22:13 29:3 56:22
BRASS, BRONZE	6:9 9:16 10:15 17:3 35:17	ELECTROLYSIS	34:14 40:51 49:26
BUSINESS CARDS	47:16	ENGINES	
CHANDLERS		Bearings, seizing	29:10
British	55:10	Comparisons	15:6 19:12 19:15
Thomas Foulkes	16:11 20:12 22:10 24:17 26:6	Change to fresh water cooling	43:95
Charts	29:17	Exhausts	12:8 14:5 15:7 18:16 23:5 25:5 28:7 32:13
COCKPIT, table, cushions	35:8 45:110	34:13 35:12 35:13 37:16 39:35 42:80 42:90
Hatch, additional	47:11	43:97 44:102 44:105 45:111 47:12 56:23 57:33
COMPUTERS, CALCULATORS	42:82 44:100 52:53		
COVERS	37:3		
DEALERS	9:2 9:13 10:16 11:9 12:4 12:6 14:11		
.....	16:3 18:6 21:14 25:1 26:1 26:2 27:6		

The format of entries in this index is NN:PP where
NN is the newsletter number and PP the page.

TOG NEWS INDEX

Issues 1 - 60 (FALL 1993)

Exhaust check valve	36:11 42:87	Deck	4:4 8:4 9:3 10:2 24:16 38:15 44:105
Fuel filter	22:13 27:9 47:13	Hatch	47:11
Heat Exchanger	38:13	Hull/deck joint	2:2 23:11 25:17 29:1 56:22 58:50
Instruments	57:33	Mast step	33:14
Mounts	8:10 9:3 9:11 10:16	Portlights	8:5 25:16 29:1 44:105
Oil, oil filters	33:15 47:13 47:14	Stanchion base	23:11
Overheating	22:13	LIFE RAFTS	8:11 18:8 25:6 28:6 38:7 47:15
Perkins	5:8 6:10 7:9 13:1 13:5 13:8 14:8 15:6	LORAN	8:13 12:7 21:5 24:9 32:16 41:61
	16:8 16:10 17:10 22:13 22:14 23: 3 23:16	Apelco	40:46
	29:9 34:9 37:12 38:13 44:102 56:22	Furuno	40:44 41:61
Removal of	29:11	Micrologic	13:5 19:12 20:4 28:15 49:26
Volvo	14:10 34:15	Nelco	21:10
Water pump	34:15 40:45 42:84	Raynav	38:7
Yanmar	11:10 13:1 14:8 15:6 16:10 17:8 21:11	Raytheon	42:87
	22:13 24:11 27:9 36:10 37:16 38:12 42:87 43:96	Sitex	12:7 22:9 23:7 24:9
	45:112 45:113 47:13 52:55 54:8	MAST	7:3 32:15
EPOXY	32:3 32:5 32:6 33:6	Change of	22:5 26:1 55:9
GALLEY STOVES		Climbing	19:21 19:22
Dickinson	9:6	Corrosion	43:97
Force 10	47:12	Deck stepped	22:14
Kenyon	9:13 11:10 12:7 22:10	Dry Rot, mast & spreader	14:10 49:27 55:9
Shipmate	13:5 14:8 23:7 28:6	Position of	17:1 18:17 22:5 25:3
Taylor	14:8	Rake	3:2 18:17 22:15 23:2 25:14 26:2 24:17
Traveler	7:4	Tang fittings	43:94 47:15
GLOBAL POSITIONING (GPS)	56:20	Vibration	20:14
GRAND DEER CATALOGUE	54:2 59:54	MOTOR SAILING	28:17 38:12
HARRIS, ROBERT	38:1 41:56	PERFORMANCE	
HARRIS, T ODD	14:8 17:2 19:1 23:2 26:15	Under power	3:5 5:4 7:9 12:5 14:10 16:10 17:8 18:4 24:10
	28:15 28:16	Sailing	7:11 9:5 13:5 16:4 18:4 20:15 23:10
HEAD, Holding tank	22:14 28:6 43:97 47:13 57:35 58:51		24:9 24:10 25:6 26:7 28:10
HEATERS		PERRY, ROBERT	18:4 19:8 21:15 22:5 25:3
Cabin	6:5 9:6 12:7 14:8 16:4 21:10 22:10 28:7		25:4 27:1 27:5 38:3 45:109
	28:12 28:14 30:8 34:10 38:6 40:44 40:46	PROBLEMS	
	42:88 44:100 47:13 49:29	Ballast Void	26:13 29:16
Water	5:9 7:3 16:3 18:9 18:11 18:12 23:14 33:7	Bedding Compound, lack of	24:16
	34:10 37:13 40:44 41:59 42:79 47:12 52:55 55:15	Bulkhead separation	12:8
INSTRUMENTS	41:61 51:43 51:44 52:50	Cabin Overhead	32:17
Combi (IMI)	23:7 29:4	Cutlass Bearing	33:13
Datamarine	13:5 21:9 28:14	Dorade, loss of	14:5
Impulse	37:15	Dry Rot	5:9 6:10 8:10 9:11 10:20 14:9 31:3
Signet	13:5 28:6 36:14	Fittings, loose	36:12
SR Mariner	28:14	Hawse pipes	31:9
INSURANCE	10:8 11:4 11:5 12:10 13:7 16:4 31:9 56:18	Hoses	17:10 18:16 28:16
KNOT METERS		Hull voids	20:13 22:12 23:3
Combi	23:7 29:4	Rot beneath Dorades	33:13
Datamarine	13:5 30:8	Running lights	12:8
Signet	13:5 28:6	Shower	31:3
Walker	23:7	Shroud fittings, cracks	33:14
LADDERS	32:6 49:31 57:30	Water Line position	36:11
LEAKS	7:10 14:5 15:6 17:11	Water tank drain	4:3 5:1
Cabin	36:17 42:77	PROPELLERS	5:5 19:17 19:21 21:11 22:13
Chainplates	6:8 23:11 29:18 49:26		23:8 24:10 28:13 41:58
Companionway	23:11	Size of	3:6 4:4 5:3 5:6 16:10 17:8 38:17 47:12

TOG NEWS INDEX

Issues 1 - 60 (FALL 1993)

Replacement	60:68	Tacking angle	25:12 28:13
PUMPS, bilge	3:6 14:7	Weather helm	10:15 11:7 3:2 6:1 55:9 58:44
RACING	43:92 50:33 54:4	SAILS	2:3 3:1 7:6 35:9 39:20 41:63 41:65
RADAR		Care of	40:52 41:63 41:64
Apelco	40:46	Cruising Spinnaker	3:4 7:5 20:12 22:14 24:9 25:13
Furuno	16:10 22:9 23:14 31:13 35:14 42:87	Dutchman	45:112
Raytheon	38:7	Furling	3:4 11:6 6:2 13:1 20:12 23:6 23:16
Stern mount	58:50	25:6 25:14 28:6 28:13 42:87 45:112 52:53 57:37
Vigil	35:17 47:12	Genoa	7:5 8:11 22:14
RADIO		Lam ..	3:4 9:9 10:14 13:6 14:1 15:1 16:4 18:16 23:16 25:13
Ham	10:8 11:8 13:5 24:11 28:8 29:4 47:12	Lee	10:15 11:6 24:9
.....	31:12 35:10 38:7 40:46 55:13 57:39 59:63	North	13:5 16:4 17:12 23:7 28:13
Radio Direction Finder	23:7	Pryde	10:14 15:1 16:5 17:12 21:12 26:7
Single Sideband	22:2 28:8 29:4 47:12 47:15 58:49	27:8 28:5 29:15 36:10 47:13 51:47 55:13
VHF	13:5 23:7 28:6 32:16 47:12	Reacher, drifter	17:11 23:15
Weather fax	38:7 47:12 49:29	Spinnaker	3:4 26:8
REFRIGERATION		Thurston	13:6
Adler Barbour / Cold Machine	6:6 8:12 28:6 30:7 32:16 35:8	Ulmer	11:7
.....	35:15 40:45 40:46 43:96 48:23 15:5 16:9 22:4 22:10	SATNAV	
Crosby	13:5 18:17 28:14	Furuno / Shipmate / Walker	22:9 22:10 35:14
Cruise	38:6	Magnovox	23:12 24:9 28:6 29:4 35:10 38:6 47:12
Electric Iceman	45:111	NCS	25:6
Frost Mate	25:5	Sitex	35:14
Perkins/Spa Creek	13:11 15:4	SEACOCKS	4:3 5:1 7:2 8:6 16:8 26:9 28:16
Grunert	11:10 15:5 21:10 25:6 29:5 34:10 42:83 47:13	37:14 43:95 45:112 48:23
Icebox insulation	4:5 5:2 6:5 6:7 8:9 13:5 13:10	SECURITY	37:2 56:26
.....	14:7 15:4 17:2 26:13 26:16 58:44	SELF STEERING	2:4 31:4
Kiki (Toyota)	15:5	Alpha Marine Systems	12:7 23:11 28:14 32:16
Nova Kool	28:14	Aries	12:7 23:10 23:12 28:6 60:70
Sailor Boy	15:5 37:12 42:82	Atoms wind vane	29:5
Sea Frost	19:12 34:11 60:69	Autohelm	2:4 9:9 13:11 14:8 22:14 22:15 24:18 25:5
Technautics	6:6 11:13	27:13 28:15 29:4 33:16 35:15 37:11 40:46
RIGGING	7:6 8:9 37:15	42:88 43:97 55:12 57:35
Bobstay	7:1 26:3 34:14 37:16 41:65 45:112 47:14 48:23	Benmar	2:4 35:15
Camber spar	25:15	Cetrek / Dana	40:44 47:13 51:47 53:60
Forestays	6:2 23:15 26:7	CPT	47:13 56:20
Genoa cars	12:10	Fleming wind vane	28:11
High Aspect	2:2 6:1 8:9 8:11	Monitor wind vane	30:11 36:14 42:78
Inspection of	41:64 57:36	Orinda	16:9
Intermediate stays	6:2 21:14 25:4 26:1 26:2 29:5	Navico	38:14 42:87
Repairs	31:4	Riebandt	58:50
Running backstays	11:5 17:2 21:14 26:8 29:5	RVG vane	16:2
Running rigging	2:3 7:6 6:3 7:7 11:5 41:63	Sail-O-Mat	9:9 10:16
Short (Nor'sea) rig	2:2 12:1	Sayes	58:52
Spars	16:5 28:1	Scanmar	42:88
Spinnaker pole	25:13	Tillermaster	2:4 9:9 13:5 17:7 19:12 28:11 37:11
Stays and shrouds	25:4 35:9 35:13 57:36	Unipas	35:16
Staysail stay disconnect	26:8	SEVEN SEAS CRUISING ASSOCIATION	31:8 56:18
Terminals, swaging	15:7 26:7	SEXTANT	8:13
SAILING, HINTS	3:1 4:1 7:8 8:11 9:10 17:11 18:6 36:13	SHAFT	7:2 13:10 14:6 23:16 26:10 35:13
Downwind	3:5 19:9	Alignment	40:38 42:80 43:95
Heavy air	3:3 7:5 23:10 26:7	Coupling	4:3 5:2 6:10 7:2 8:10 11:7 14:6 23:16 25:6
Reefing	2:3 3:3 6:2 17:11 17:12 21:9 21:10 22:14 24:9 29:5	26:10 29:2 38:16 43:97 49:26 51:47 53:61 57:33 57:36

TOG NEWS INDEX

Issues 1 - 60 (FALL 1993)

Cutlass Bearings	33:13 33:14 38:13 51:47	Member in space	47:10 51:48
Lock	5:3 16:8 38:14	Membership roster	48:19 60:68
Packing Gland	4:5 5:2 6:4 7:10 17:2 25:6 32:15 34:14 41:59	Model Tayana	11:4
Seals	33:2 37:13 39:29 40:46 45:111 57:37 45:108	Newsletter	8:14 11:10 14:1 14:11 19:3 47:10 52:49
Shaft replacement	51:47 55:15	Newsletter Editor	1:2 12:11 14:12 15:8 19:23
STEERING	28:5 34:13 44:102 56:23 57:33		23:18 27:18 32:18 53:58 54:1
Emergency tiller	4:4 5:2 20:13	TEAK	4:6 14:3 16:2 34:14 41:58 60:69
Failure	19:5 20:13 28:5 42:74 42:83 55:21	Blocks	10:14 13:10
Hydraulic	2:4 4:3 8:5 28:13	Deck	6:8 7:5 8:12 9:9 12:11 33:4 38:14 41:58 47:13
Pedestal	4:3 5:8 6:3 6:10 10:16 11:7 14:6 16:9 20:14	Exterior	4:6 8:14 10:14 11:13 29:2
Rack and Pinion	4:3 15:7 23:9	Interior	4:6 9:16 10:14 11:13 34:14
Rudder	14:7 18:17 33:14 40:45 44:105 45:112	Products	14:3 21:15 25:6 26:14 29:2 49:27 51:42
Worm gear	2:3 4:3 5:1 7:1 56:21	THRUHULLS	37:15 45:112 48:23
SURVIVAL SUITS	38:7	TOPSIDES, Cleaning	42:83
TA YANG YARD	9:1	Blisters	56:21 58:51
Cooperation by	16:3 19:4	TRIP REPORTS	
Fax Information Service	45:108	Atlantic	17:7 23:9 41:68 41:70 42:78
Sea trials	21:4		53:57 57:29 58:41 59:53 60:71
Visits to	2:1 7:3 10:23 11:1 12:1 17:3 19:5	Australasia	58:47
	20:1 23:5 27:7 31:2 47:9	Bermuda	18:9 27:11 31:8 39:27 42:76 47:15
TANKAGE		Canada, West	15:7 16:6 22:7 33:12 34:6 45:113
Dip sticks	15:3 40:43 42:86	Canada, East	17:8 21:9 34:4 36:7 44:103 48:18
Fuel	19:7 31:9 37:16 38:6 51:47 53:61 58:50	Caribbean	34:6 36:9 40:49 43:92 43:93 43:94
Water	4:2 19:7 23:9 35:10 42:89		49:25 52:54 56:27 59:57 60:67
TAYANA		Central America	44:103 52:54
Commissioning	14:9 16:1 19:5 23:3 33:13 47:9	China Sea	19:5 15:7 24:8 54:4
Cruising book	22:6	Circumnavigation	53:61 56:17
CT 37	8:4 21:15 58:44	Great Lakes	17:7 31:11 31:12 48:18
Customizing	6:6 7:3 19:7 21:12 21:14 24:4 25:14	Europe	27:14 32:8 34:2 47:15 52:54
	27:8 28:5 30:4 30:10 38:6 40:48 49:30	Hawaii	21:4 22:1
Importing direct	13:9 19:2 19:13 22:8 22:9	Mexico	21:1 24:1 33:9 40:48
	23:2 26:13 26:18 27:18	Pacific	8:6 8:7 20:1 24:11 36:6 47:15 49:31 59:57
Living aboard	16:3 21:14 25:2 28:7 28:12 31:3 31:4	Panama	60:65
Name, origin	1:2 6:9 11:14	Philippines	21:4 33:8 35:1 36:5 47:15
Owners manual	55:14	Russia	51:46
Pilothouse model	9:8 10:9 13:10 28:13	U.S. East	8:1 13:3 20:2 21:11 25:2
Purchasing	22:11 36:17 45:108 49:27		25:5 25:6 32:10 33:12 34:5 35:5 37:5 39:28
Rebuilding	34:1 40:41 58:45		41:71 49:25 56:20
Recipes	56:19 59:54 55:11	U.S. South	13:3 13:4 24:12 24:15 38:7 56:20
Rendezvous	18:4 21:15 34:8 37:4 41:57 49:31 52:56	U.S. West	13:3 33:12 47:15 34:4 39:26
	54:3 55:11 56:19 57:31 58:43 59:55	U.S. COAST GUARD, problems with	21:7 48:24 50:40
Sailing dental office	4:1 7:1	VIDEOS	49:25 49:31
Ships Store	54:2 55:10 56:18 57:30 58:42 59:54 60:66	WATER FILTER/PURIFIER	8:14 9:6 29:18 33:15
Transatlantic Rally	44:99 45:113	WATER LINE	60:69
T47	45:109 56:21 57:32	WATER MAKER	34:11 38:6 45:111 49:29 52:50 57:37
T52 and T55	17:3 55:14 57:32	WINCHES	6:8 7:4 7:7 13:7 16:5 17:7 23:6 28:6
Upgrading	56:20 56:22		28:14 29:13 57:36 60:69
V42	17:3 35:6 35:7 49:31 50:34 51:47 55:14	WINDLASS	6:8 28:14 29:13 43:97 44:100
TAYANA OWNERS GROUP	1:1 11:4 12:8 14:1 19:1 19:10 25:1		44:105 47:12 52:53 58:50
Burgee	13:4 18:3 21:15		
Buyers guide	21:15		
Chesapeake Bay group	47:16 49:31 52:56		