









	PIPING OF WASTE WATER SYSTEM
	PIPING OF HOLDING TANK SYSTEM
	VENTILATOR
	VENT FILTER

<input checked="" type="checkbox"/>	DECK SUCTION OF HOLDING TANK
	SHOWER PUMP FLUJET 4105-143A
	Y-VALVE
	STRAINER
	MANUAL PUMP HENDERSDN MH0510
	MACERATOR PUMP JABSCD 18590-1091
	THRUHULL & BALL VALVE
<input checked="" type="checkbox"/>	CHECK VALVE



Certified ISO 9001 by



CLIENT : TAYANA-D48-107
 TITLE : WASTE WATER SYSTEM
 DRG NO. : D48-107-2
 SCALE : N/A
 DATE : 2007/12/05
 DRG BY : Cherry



TAYANA YACHT BUILDING CO., LTD.